Wood Destroying Insect Inspection Report Notice: Please read important consumer information on page 2.				
	neral information inspection Company, Address & Phone	Company's Business Lic No.	Date of Inspection	1
Force Termite & Pest Control Inc 292 STUYVESANT AVENUE LYNDHURST, NJ 07071 800-522-4511		91273A		7/2015
		Address of Property Inspected TOWNSHIP OF ROCHELLE PARK 49 E Passaic St Rochelle Park, NJ 07662-3305		
Inspector's name, Signature & Certification, Registration or Lic # JAMES MOLZAN #58931-A		Structure(s) Inspected HOME,BARN		
Section II. Ins	pection Findings This report is indicative of the condition of the	e above identified structure(s) on the da	ate of inspection and is	not to be construed as a
guarantee or warranty against latent, concealed, or future infestations or defects. Based on a careful visual inspection of the readily accessible areas of the structure (s) inspected:				
X A. No Visible evidence of wood destroying insects was observed.				
B. Visible evidence of wood destroying insects was observed as follows:				
1. Live Insects (description & location):				
2. Dead insects, insect parts, frass, shelter tubes, exit holes, or staining (description and focation):				
3. Visible damage from wood destroying insects was noted as follows (description and location):				
NOTE: This is not a structural damage report. If box B above is checked, it should be understood that some degree of damage, including hidden damage, may be present. If any questions arise regarding damage indicated by this report, it is recommended that the buyer or any interested parties contact a qualified structural				
professional to determine the extent of damage and the need for repairs. Yes No X It appears that the structure(s) or a portion thereof may have been previously treated. Visible evidence of possible previous treatment:				
163 [] (40 [X] It appeals that the situation (5) of a polition thereof may have been previously beared. Visible evidence of possible previous heatman.				
The inspecting company can give no assurances with regard to work done by other companies. The company that performed the treatment should be contacted for information on treatment and any warranty or service agreement which may be in place.				
Section III. Recommendations				
No treatment recommended: (Explain if Box B in Section II is checked)				
Recommend treatment for the control of:				
Section IV. Obstructions and Inaccessible Areas The inspector may write out obstructions				
The following areas of the structure(s) inspected were obstructed or inaccessible: Fig.			or use the following 1. Fixed ceiling	optional key: 13. Only visual access
Sasement 1-3-4-5-6-7-8-9-11-13-17-24			2. Suspended ceiling	14. Cluttered condition
<u>, </u>			Fixed wall covering Floor covering	15. Standing water 16. Dense vegetation
Attic				17. Exterior Siding
Garage				18. Window well covers
X Exterior	11–13-17–24 7. Stored items 19. Wood pile 8. Furnishings 20. Snow			
Porch	Unsate conditions			
Addition X Other				22. Rigid foam board 23. Synthetic stucco
LA OTHER SHAFFEE			11. Limited access 12. No access beneath	24, Duct work, plembing, and/or wiring
Section V. Additional Comments and Attachments (these are an integral part of the report) No evidence of Subterranean Termites or any wood destroying insects observed.				
Attachments				
Signature of Seller(s) or Owner(s) if refinancing. Seller acknowledges that all information regarding W.D.I. infestation, damage, repair, and treatment history has				
been disclosed to	o the buyer.	x		
^				

Form NPMA-33 (09/01/04) © 2004 National Post Management Association. All Rights Reserved. No reproduction of this form is permitted without the express permission of NPMA. Form NPCA-1 is obsolete after 12/01/04.

Page 1 of 2